

BUREAU OF ENERGY EFFICIENCY



Examination	Registration	No.	:	EA-15189
Accreditation	Registration	No.	:	AEA-0244

Certificate of Accreditation

This is to certify that Mr./Ms	Chandra Kumar	having its trade/registered
office at Chennal has been	given accreditation as	s accredited energy auditor. The
certificate shall be effective from		

The certificate is subject to the provisions of the Bureau of Energy Efficiency (Qualifications for Accredited Energy Auditors and Maintenance of their List) Regulations, 2010.

This certificate shall be valid until it is cancelled under regulation 9 of the Bureau of Energy Efficiency (Qualifications for Accredited Energy Auditors and Maintenance of their List) Regulations, 2010

On cancellation, the certificate of accreditation shall be surrendered to the Bureau within fifteen days from the date of receipt of order of cancellation.

Your name has been entered at AEA No... 0244... in the register of list of accredited energy auditors. Your name shall be liable to be struck out on the grounds specified in regulation 8 of the Bureau of Energy Efficiency (Qualifications for Accredited Energy Auditors and Maintenance of their List) Regulations, 2010.

Given under the seal of the Bureau of Energy Efficiency, Ministry of Power, this 12th day of __January 2016.

Secretary, Bureau of Energy Efficiency

New Delhi

Dr.M.JEYAKUMAR, M.E..Ph.D.

CHRIST THE KING ENGINEERING COLLEGE, Chikkarampalayam Village, Karamadai, Mettupalayam Taluk,

Combatore - 641 104.



Observed Implementation AY 2019-20

Details of energy efficiency improvement measures implemented, investment made and savings in energy achieved and progress made in the implementation of other recommendations

Implemented

S.No	Description of Energy Efficiency Improvement Measures	Category	Investment (Lakhs INR)	Verified Money savings (in Lakhs INR)	Verified Energy savings (in kWH)	Unit in kWH	remarks
1	UNDER STUDY					. 8	

Under implementation as declared by clients-AY 2019-20

S.No	Description of energy efficiency improvement measures	Category	Investment	Proposed Money savings (in Lakhs	Proposed energy savings	Unit in Lac KWH	Status of implementation
			(lac INR)	INR)	(in kWH)		The state of the s
1	Replacement of resistive fan regulators		30000.00	0.05	500	500	Under progress

KARAMADAI Z COIMBATORE 641 104

(Signature of client-with seal)

Dr.M.JEYAKUMAR, M.E..Ph.D.

PRINCIPAL

CHRIST THE KING ENGINEERING COLLEGE,

Chikkarampalayam Village,

Karamadai, Mettupalayam Taluk,

Coimbature - 641 104.

For SUBARNAS PROFESSIONAL SERVICES LLP

FAZYSVM, COIMBATORE 641 015 Subarnaas@gmail.com

AUTHORISED SIGNATORY

Observation on recommended energy savings (AY 2019-20)

Details of action taken on recommendation of pre assessments by consultant for improving energy efficiency

S.No	Energy efficiency improvement measures (suggested categories of areas of energy efficiency improvement for obtaining details	Investment in INR lacs	Reason for not implementing of measures/	life cycle	<i>F</i>	Annua	l energ	y savings in II	NR lacs
	of energy savings)	likely completion	years	oil	gas	coal	electricity	others	
1	Replaced wired chokes with electronic chokes	0.50	Pandemic lock down	5					
		The second secon		·					
							and the second s		

Signature

1 Should

Name of Authorized person

: DT.M. JEYAKUMAR

Client Name : CHRIST THE KING ENGINEERING

Signature OF EA F 15139

COIMBATORE 641 015

ubarnaas@gmail.com

- 1. Estimate the predicted life of measure, meaning the number of years the level of first year energy savings of even larger account will materialize
- 2. Life of commercial units of liters, kg, tones, normal cubic meter, KWH or MWH and indicate the unit, indicate the anticipated potential in energy savings

(Signature of client with seal)

Dr.M.JEYAKUMAR, M.E..Ph.D.
PRINCIPAL
CHRIST THE KING ENGINEERING COLLEGE,
Chikkarampalayam Village,

COIMBATORE

Karamadai, Mettupalayam Taluk, Coimbatore - 641 104. For SUBARNAS PROFESSIONAL SERVICES LE

AUTHORISED SIGNATORY

Observed Implementation AY 2020-21

Details of energy efficiency improvement measures implemented, investment made and savings in energy achieved and progress made in the implementation of other recommendations

Implemented

S.No	Description of Energy Efficiency Improvement Measures	Category	Investment (Lakhs INR)	Verified Money savings (in Lakhs INR)	Verified Energy savings (in kWH)	Unit in kWH	remarks
1	46W Tube lights replaced with 16W LED –50 Nos	Lighting	0.4	0.244	3600	3600	From April 2017 to March 2018

Under implementation as declared by clients-2020-21

COIMBATORE 641 015

ரித்தை@gmail.com

S.No	Description of energy efficiency improvement measures	Category	Investment (Iac INR)	Proposed Money savings (in Lakhs INR)	Proposed energy savings (in kWH)	Unit in Lac KWH	Status of implementation
1		(Covid pandemic	and no imple	ementation		

(Signature of client with seal)

Dr.M.JEYAKUMAR, M.E..Ph.D.
PRINCIPAL
CHRIST THE KING ENGINEERING COLLEGE,
Chikkarampalayam Village,

Karamadai, Mettupalayam Taluk, Coimbatore - 641 104. For SUBARNAS PROFESSIONAL SERVICES LLI

ANTHORISED SIGNATOR

WING ENGINE WARAMADAI COUMBATORE 691 109 * 30370

Observation on recommended energy savings (AY 2020-21)

Details of action taken on recommendation of pre assessments by consultant for improving energy efficiency

S.No	Energy efficiency improvement measures(suggested categories of areas of energy efficiency improvement for obtaining	Investment in INR lacs	Reason for not implementing of measures/	life cycle years	A	Innua	l energ	y savings in II	VR lacs
transcription could clar	details of energy savings)		likely completion	,	oil	gas	coal	electricity	others
1	Installation of Solar water heater in Hostel	2.8	Recommended						
2	Replacement of fluorescent tube lights with CFL Lamps in classrooms	0.875	Recommended						
3	Installation of UPS batteries	2.15	Recommended						

Signature

Name of Authorized person

: DY. M. JEYAKUMAR

Client Name : CHRIST THE KING ENGINEERING

U. CHANGERKUMAR Energy Auditor

Signature OF EA EA - 15189

s@gmail.com

COIMBATORE 641 015

1. Estimate the predicted life of measure, meaning the number of years the level of first year energy savings of even larger account will materialize

2. Life of commercial units of liters, kg, tones, normal cubic meter, KWH or MWH and indicate the unit, indicate the anticipated potential in energy savings

(Signature of client with seal)

Dr.M.JEYAKUMAR, M.E..Ph.D. PRINCIPAL

CHRIST THE KING ENGINEERING COLLEGE, Chikkarampalayam Village, Karamadai, Mettupalayam Taluk, Coinbatore - 641 104. For SUBARNAS PROFESSIONAL SERVICES LLF

ANTHORISED SIGNATORY

KARAMADAI RECOMBATORE COMBATORE COMB

Observed Implementation-AY 2021-22

Details of energy efficiency improvement measures implemented, investment made and savings in energy achieved and progress made in the implementation of other recommendations

Implemented

	Description of Energy		Investment	Verified Money savings	Verified Energy	Unit in	
S.No	Efficiency Improvement Measures	Category	(Lakhs INR)	(in Lakhs INR)	savings (in kWH)	kWH	remarks
1	40W Tube lights replaced with 20W CFL – 50 Nos	Lighting	0.4	0.288	3600	3600	From April 2021 to March
2	Solar Water Heater – 500 lt	Water Heating	2.8	0.45	5600	5600	2022
3	Installation of UPS – 10 KVA	Electrical Energy	2.15	0.096	1200	1200	

Under implementation as declared by clients AY 2021-22

5.No	Description of energy efficiency improvement measures	Category	Investment	Proposed Money savings (in Lakhs INR)	Proposed energy savings (in kWH)	Unit in Lac KWH	Status of implementation
1	Solar Water Heater – 500 lt * 2	Water Heating	5.6	0.9	1120	1120	Under Progress in a phased manner
2	Installation of UPS – 10 KVA	Electrical Energy	2.15	0.096	1200	1200	

(Signature of client with seal)

Dr.M.JEYAKUMAR, M.E..Ph.D. PRINCIPAL CHRIST THE KING ENGINEERING COLLEGE, Chikkarampalayam Village, Karamadai, Mettupalayam Taluk, Coimbatore - 641 104.

For SUBARNAS PROFESSIONAL SERVICES LLF VM, COIMBATORE 641 015

naas@gmail.com

AUTHORISED SIGNATORY

KARAMADAI\
COIMBATORE

Observation on recommended energy savings (AY 2021-22)

Details of action taken on recommendation of pre assessments by consultant for improving energy efficiency

S.No	Energy efficiency improvement measures(suggested categories of areas of energy efficiency improvement for obtaining	Investment In INR lacs	Reason for not implementing of measures/	life cycle years	^	\nnua	l energ	y savings in Iñ	NR facs
	details of energy savings)		likely completion		oil	gas	coal	electricity	others
1	Installation of Solar water heater in Canteen	2.8	Recommended	15	Not applicable				
2	Replacement of fluorescent tube lights with CFL Lamps in classrooms	0.875	Recommended	7				The state of the s	
3	Replacement of SV lamp (street lights) with tube lights		Recommended	7			1120		
4	Installation of UPS batteries	2.15	Recommended	5	1			1200	

Signature

Name of Authorized person

Client Name ! CHRIST THE KING ENGINEERING

Signature of EA

VM, COIMBATORE 641 015

ubarnaas@gmail.com

- 1. Estimate the predicted life of measure, meaning the number of years the level of first year energy savings of even larger account will materialize
- 2. Life of commercial units of liters, kg, tones, normal cubic meter, KWH or MWH and indicate the unit, indicate the anticipated potential in energy savings

(Signature of client with seal)

Dr.M.JEYAKUMAR, M.E.Ph.D. PRINCIPAL CHRIST THE KING ENGINEERING COLLEGE, Chikkarampalayam Village,

Karamadai, Mettupalayam Taluk, Coimbatore - 641 104.

For SUBARNAS PROFESSIONAL SERVICES LLP

COIMBATORE

Observed Implementation-2022-23

Details of energy efficiency improvement measures implemented, investment made and savings in energy achieved and progress made in the implementation of other recommendations

Implemented

	Description of Energy No Efficiency Improvement Measures		Investment	Verified Money savings	Verified	Unit in	
S.No		Category	Category (Lakhs INR)		Energy savings (in kWH)	kWH	remarks
1	40W Tube lights replaced with 20W CFL –25 Nos	Lighting	0.2	0.144	1800	1800	From April 2022 to March 2023
2	Solar Water Heater – 500 lt x 2	Water Heating	5.4	0.9	1120	1120	
3	Installation of UPS – 10 KVA	Electrical Energy	2.15	0.096	1200	1200	

Under implementation as declared by clients-2022-23

S.No	Description of energy efficiency improvement measures	Category	Investment (lac INR)	Proposed Money savings (in Lakhs INR)	Proposed energy savings (in kWH)	Unit in Lac KWH	Status of implementation
1	Solar Water Heater – 500 lt * 1	Water Heating	2.8	0.9	1120	1120	Under Progress in a phased manner
2	Installation of UPS – 10 KVA	Electrical Energy	2.15	0.096	1200	1200	

(Signature of elient with seal)

Dr.M.JEYAKUMAR, M.E..Ph.D.
PRINCIPAL

CHRIST THE KING ENGINEERING COLLEGE, Chikkarampalayam Village, Karamadai, Mettupalayam Taluk, Coimbatore - 641 104. For SUBARNAS PROFESSIONAL SERVICES LL

WITHORISED SIGNATORY

JSVM, COIMBATORE 641 015 subarnaas@gmail.com

Observation on recommended energy savings (as on Nov 2022-23)

Details of action taken on recommendation of pre assessments by consultant for improving energy efficiency

S.No	Energy efficiency improvement measures(suggested categories of areas of	Investment in INR lacs	Reason for not implementing of measures/	life cycle	1	Annua	al energ	gy savings in If	NR lacs
	energy efficiency improvement for obtaining details of energy savings)	IN IIVK IaCS	likely completion	years	oil	gas	coal	electricity	others
1	Replacement of Tube lights & CFL Lamps with LED lights in classrooms & admin block	1.25	Recommended	7				0.876	and a second stream of the
2	Replacement of SV lamp (street lights) with LED lights	0.8	Recommended	7	Not	applic	cable	0.085	
3	Installation of UPS batteries	2.15	Recommended	5				0.120	

Signature

Name of Authorized person

Dr.M. SEYA KUMAR

Client Name ! CHRIST THE ICING ENGINEERING

U. WHATORA KUMAR Energy Auditor

Signature OF FA

1. Estimate the predicted life of measure, meaning the number of years the level of first year energy savings of even larger account will materialize

2. Life of commercial units of liters, kg, tones, normal cubic meter, KWH or MWH and indicate the unit, indicate the anticipated

potential in energy savings

FOT SUBARNAS PROFESSIONAL SERVICES LLP

bvM, COIMBATORE 641 015

(Signature of client with seal)

Dr.M.JEYAKUMAR, M.E.,Ph.D.
PRINCIPAL

CHRIST THE KING ENGINEERING COLLEGE, Chikkarampalayam Village,

Karamadai, Mettupalayam Taluk, Coimbatore - 641 104.

KARAMADAI COIMBATORE 641 104

Observed Implementation-2023-24

Details of energy efficiency improvement measures implemented, investment made and savings in energy achieved and progress made in the implementation of other recommendations

Implemented

C 81	Description of Energy Efficiency		Investment	Verified Money savings	Verified Energy	Unit in	
S.No	Improvement Measures	Category	(Lakhs INR)	(in Lakhs INR)	savings (in kWH)	kWH	remarks
1	Installation of LED tube lights in place of Florescent tube lights in Main Block – 120 nos	Electrical Energy	0.54	0.384	3840	3840	From April 2023 to March 2024
2							
3		•					

Under implementation as declared by clients-2023-24

S.No	Description of energy efficiency improvement measures	Category	Investment (lac INR)	Proposed Money savings (in Lakhs INR)	Proposed energy savings (in kWH)	Unit in Lac KWH	Status of implementation
1	Installation of LED tube lights in place of Florescent tube lights in Main Block – 100 nos	Electrical Energy	0.45	0.32	3200	3200	Implementation under progress

KARAMADAI COIMBATORE COIMBATORE 641 104

(Signature of Afrent with seal)

Dr.M.JEYAKUMAR, M.E..Ph.D.

PRINCIPAL

CHRIST THE KINC ENGINEERING COLLEGE,

Chikkarampalayam Village,

Karamadai, Mettupalayam Taluk,

Combatore - 641 104.

SUBJENAS SUB SUBJENAS SUBJENAS SUBJENAS SUBJENAS SUBJENAS SUBJENAS SUBJENAS

For SUBARNAS PROFESSIONAL SERVICES LL

AUTHORISED SIGNATORY

Observation on recommended energy savings (2023-24)

Details of action taken on recommendation of pre assessments by consultant for improving energy efficiency

5.N 0	Energy efficiency improvement measures (suggested categories of areas of energy efficiency improvement	Investment	Reason for not implementing of measures/	life cycle	А	nnual e	energy s	savings in INR	lacs
	for obtaining details of energy savings)	ii	likely completion	70015	oil	gas	coal	electricity	others
1	Replacement of CFL Lamps with LED lights in classrooms – 120 nos out of 22C completed and 100 nos in progress	1.00	More than 50% activity completed and	7				0.704	
2	Replacement of Window A/c to Energy efficient inverter A/c – 2 nos	1.0	balance in progress. A/C replacement in	8	NOT APPLICABLE		0.768		
3	Replacement of old electric fans with BLDC fans phase 1 labs	0.90	progress	10				0.752	

Signature

Name of Authorized person

DAMM. JEYAKUMAR

Client Name : CHRUT THE KING ENGINEERING

Signature of EA Energy Auditor

* PG2/SVM, COIMBATORE 641 015

subarnaas@gmail.com

1. Estimate the predicted life of measure, meaning the number of years the level of first year energy savings of even larger account will materialize

2. Life of commercial units of liters, kg, tones, normal cubic meter, KWH or MWH and indicate the unit, indicate the anticipated

potential in energy savings

(Signature of client with seal)

Dr.M.JEYAKUMAR, M.E.Ph.D.

PRINCIPAL CHRIST THE KING ENGINEERING COLLEGE, Chikkarampalayam Village, Karamadai, Mettupalayam Taluk, Coimbatore - 641 104.


For SUBARNAS PROFESSIONAL SERVICESLL

KARAMADAI COIMBATORE




ENERGY STUDY

A. RMS POWER OVERVIEW TABLE





B. DEMAND





For SUBARNAS PROFESSIONAL SERVICES LLP

UBARNAS PROFESSIONAL SERVICES LLP FA2 JSVM

COIMBATORE 641 015 subarnaas@gmail.com


AUTHORISED SIGNATORY

Dr.M.JEYAKUMAR, M.E..Ph.D.
PRINCIPAL
CHRIST THE KING ENGINEERING COLLEGE,
Chikkarampalayam Village,
Karamadai, Mettupalayam Taluk,
Combatore - 641 104.






C. FUNDAMENTAL POWER





D. V,A, HARMONICS





SUBA

For SUBARNAS PROFESSIONAL SERVICES LLP

AUTHORISED SIGNATORY

SUBARNAS PROFESSIONAL SERVICES LLP FA2 JSVM


COIMBATORE 641 015 subarnaas@gmail.com



Dr.M.JEYAKUMAR, M.E.,Ph.D.
PRINCIPAL
CHRIST THE KING ENGINEERING COLLEGE,
Chikkarampalayam Village,
Karamadai, Mettupalayam Taluk,
Colmbatore 641 104.




E. UNBLANACE





Power Quality Study

F. Voltage harmonics



For SUBARNAS PROFESSIONAL SERVICES LLP

AUTHORISED SIGNATORY

SUBARNAS PROFESSIONAL SERVICES LLP

FA2 JSVM COIMBATORE 641 015 subarnaas@gmail.com




Dr.M.JEYAKUMAR, M.E..Ph.D.
PRINCIPAL

CHRIST THE KING ENGINEERING COLLEGE, Chikkarampalayam Village. Karamadat. Mettupalayam Taluk, Combatore - 641 104.




A Sampath Kumar

G. Current Harmonics



H. Power Quality Health



For SUBARNAS PROFESSIONAL SERVICES LLP

AUTHORISED SIGNATORY

SUBARNAS PROFESSIONAL SERVICES LLP

FA2 JSVM COIMBATORE 641 015 subarnaas@gmail.com

Dr.M. JEYAKUMAR, M.E. Ph.D.
PRINCIPAL

CHRIST THE KING ENGINEERING COLLEGE;
Chikkarampalayam Village.
Kasamadai Mertupalayam faluti;
Cumpalayae oa 1 104







SUBARNAS PROFESSIONAL SERVICES LLP

FA 2 JSVM, RAMANUJA NAGAR COIMBATORE 641015 subarnaas@gmail.com

THERMAL IMAGING STUDY OF SUBSTATION

IR PHOTOS ON REAL TIME

CHRIST THE KING ENGINEERING COLLEGE 158/3, Cecilia Gardens Onnipalayam Road, Mettupalayam to Airport Road Via Karamadai, Karamadai, Tamil Nadu 641104



Dr.M.JEYAKUMAR, M.E..Bh.D.
PRINCIPAL
CHRIST THE KING ENGINEERING EDILEGE,
Chikkarampalayam VIIISHE;
Karamadan Mempatayam Fahak,
Combanora - 641 Fem



Inspected By: U Chandra Kumar A Sampath Kumar EA 15189

Inspection Date:	29 March 202410:26:37 AM	Area	2
Location	10.20.07740	Compass	
Description		Weather Conditions:	
Indoor Air Temperature		Outdoor Air Temperature	
Indoor Relative Humidity:		Outdoor Relative Humidity:	
Dew Point (inside):		Wind Speed	
Problem		Repair Priority:	
Emissivity:	0.95	Reflected Temperature:	71.6 °F
Camera Manufacturer	Fluke Thermography	Camera:	Ti400-14110349

17	
$ \begin{array}{ccc} & \text{Max} = 9 \\ & \text{Avg} = 37 \end{array} $	61
Min = \$4	19
	A Short with the
The same of	50) Insulates and
84.4	Carried IV

AT000733.IS2



Visible Light Image

For SUBARNAS PROFESSIONAL SERVICES LLP

AUTHORISED SIGNATORY

SUBARNAS PROFESSIONAL SERVICES LLP

FA2 JSVM

COIMBATORE 641 015

subarnaas@gmail.com

KARAMADAI COIMBATORE 641 104 CO


Dr.M.JEYAKUMAR, M.E..Ph.D PRINCIPAL CHRIST THE KING ENGINEERING COLLEGE,

Christ the King Engineering College Chikkarampalayam Village, Karamadai. Mettupalayam Taluk; Coimbatore - 641 104.




Inspection Date:	29 March 202410;26:58 AM	Area	
Location		Compass	
Description		Weather Conditions:	
Indoor Air Temperature		Outdoor Air Temperature	
Indoor Relative Humidity:		Outdoor Relative Humidity:	
Dew Point (inside):		Wind Speed	79
Problem		Repair Priority:	
Emissivity:	0.95	Reflected Temperature:	71.6 °F
Camera Manufacturer	Fluke Thermography	Camera:	Ti400-14110349

PROFE



AT000734.IS2



Visible Light Image

For SUBARNAS PROFESSIONAL SERVICES LLP

PROFESSIONAL SERVICES LLP

FA2 JSVM

Allahoreen elenation

COIMBATORE 641 015

subarnaas@gmail.com

KARAMADAI COIMBATORE 641 104

Dr.M.JEYAKEWAR, M.E.Ph.D

PRINCIPAL
CHRIST THE KING ENGINEERING COLLEGE,
Chikkarampalayam Village,
Karamadai, Mettupalayam Taluk,
Coimbatore - 641 104.



Inspected By: U Chandra Kumar A Sampath Kumar EA 15189

Inspection Date:	29 March 202410:27:28 AM	Area	
Location			
Description	-	Compass	2.1
Indoor Air Temperature		Weather Conditions:	
mood All Temperature		Outdoor Air	
Indoor Relative Humidity:		Temperature	
mader Relative Humidity:		Outdoor Relative	
Dew Point (inside):	-	Humidity:	
Problem		Wind Speed	
Emissivity:		Repair Priority:	
Linissivity.	0.95	Reflected	71.6 °F
Camera Manufact		Temperature:	/ 1.0 F
Camera Manufacturer	Fluke Thermography	Camera:	Ti400-14110349

	Ma	0x = 90	0.7		
di de la constanti de la const	Av	o = 89	0.1		
000	jun	g = 89 n = 85	8	M. D. Harris	HEAL PRINCIPAL STATES
		86.1			
30 30	NEW TOTAL			ACCUPATION OF	
				193	
		40			

Visible Light Image

FOR SUBARNAS PROFESSIONAL SERVICES LLP

BARNAS PROFESSIONAL SERVICES LLP

FA2 JSVM

AUTHORISED SIGNATORY

COIMBATORE 641 015

subarnaas@gmail.com

KARAMADAI COIMBATORE 641 104

Dr.M.JEYAKUMAR, M.E.Ph.D.

PRINCIPAL
CHRIST THE KING ENGINEERING COLLEGE,
Chikkarampalayam Village,
Karamadai Mettupalayam Taluk,
Communicie 641 104




Inspected By: U Chandra Kumar A Sampath Kumar EA 15189

Inspection Date:	29 March 202410:27:57 AM	Area	
Location		Compass	
Description		Weather Conditions:	
Indoor Air Temperature		Outdoor Air Temperature	
Indoor Relative Humidity:		Outdoor Relative Humidity:	
Dew Point (inside):		Wind Speed	
Problem		Repair Priority:	
Emissivity:	0.95	Reflected Temperature:	71.6 °F
Camera Manufacturer	Fluke Thermography	Camera:	Ti400-14110349

	Max = Avg = Nio =	94.5 87.5 94.9	
	88	11	
83.9	100	P	

AT000736.IS2



Visible Light Image

FOI SUBARNAS PROFESSIONAL SERVICES LLP

AUTHORISED SIGNATORY

BARNAS PROFESSIONAL SERVICES LLP

FA2 JSVM

COIMBATORE 641 015

subarnaas@gmail.com

KARAMADAI
COIMBATORE
641 104

COLUMN TO COLUMN

Dr.M.JEYAKUMAR, M.E..Ph.D.
PRINCIPAL

CHRIST THE KING ENGINEERING COLLEGE, Chikkarampalayam Village, Karamadai, Mettupalayam Taluk, Combatore - 641 104.



Inspection Date:	29 March 202410:28:20 AM	Area	
Location		Compass	
Description		Weather Conditions:	-
Indoor Air Temperature		Outdoor Air Temperature	
Indoor Relative Humidity:		Outdoor Relative Humidity:	
Dew Point (inside):		Wind Speed	
Problem		Repair Priority:	
Emissivity:	0.95	Reflected Temperature:	71.6 °F
Camera Manufacturer	Fluke Thermography	Camera:	Ti400-14110349

	Max = 89.4 Avg = 87.5 Min = 84.5	
	0//38	94.1
83.5		

AT000737.IS2



Visible Light Image

For SUBARNAS PROFESSIONAL SERVICES LLP

AUTHORISED SIGNATORY

RNAS PROFESSIONAL SERVICES LLP

FA2 JSVM

COIMBATORE 641 015

subarnaas@gmail.com

KARAMADAI COIMBATORE 641 104 CO

Dr.M.JEYAKUMAR, M.E., Ph.D

PRINCIPAL
CHRIST THE KING ENGINEERING COLLEGE,
Chikkarampatayam Village,
Karamadai, Mettupatayam Taluk,
Combatore - 641 104.



Inspected By: U Chandra Kumar A Sampath Kumar EA 15189

Inspection Date:	29 March 202410:29:00 AM	Area	
Location		Compass	
Description		Weather Conditions:	
Indoor Air Temperature		Outdoor Air Temperature	
Indoor Relative Humidity:		Outdoor Relative Humidity:	
Dew Point (inside):		Wind Speed	-
Problem		Repair Priority:	
Emissivity:	0.95	Reflected Temperature:	71.6 °F
Camera Manufacturer	Fluke Thermography	Camera:	Ti400-14110349

	Max = 92.3	
	Avg = 89 6 Min = 88.5	
	89.3	
	The second secon	
83.9		
	The state of the s	

Visible Light Image

For SUBARNAS PROFESSIONAL SERVICES LLP

AUTHORISED SIGNATORY

ARNAS PROFESSIONAL SERVICES LLP

FA2 JSVM

COIMBATORE 641 015

subarnaas@gmail.com



Dr.M.JEYAKUMAR, M.E.Ph.D.
PRINCIPAL

CHRIST THE KING ENGINEERING COLLEGE, Chikkaramparayam Village, Karamadar, Meduparayam Taluk,

Combaiore - 641 104.



Inspection Date:	29 March 202410:29:49 AM	Area	
Location		Compass	
Description		Weather Conditions:	
Indoor Air Temperature		Outdoor Air Temperature	
Indoor Relative Humidity:		Outdoor Relative Humidity:	
Dew Point (inside):		Wind Speed	
Problem		Repair Priority:	7.0
Emissivity:	0.95	Reflected Temperature:	71.6 °F
Camera Manufacturer	Fluke Thermography	Camera:	Ti400-14110349

	Max = 121.8 Avg = 97.9 Min = 89.4	142.8	
	98.1		
		Section 12	
88.7			STATE OF THE PARTY

AT000739.IS2



Visible Light Image

FA2 JSVM

COIMBATORE 641 015

subarnaas@gmail.com



Dr.M.JEVAKUMAR, M.E..Ph.D.
PRINCIPAL

CHRIST THE KING ENGINEERING COLLEGE, Chikkarampalayam village.


Karamada: Mettupatayam Taluk; Coimbatore - 041 104.



Inspection Date:	29 March 202410:30:28 AM	Area	
Location		Compass	
Description		Weather Conditions:	
Indoor Air Temperature		Outdoor Air Temperature	
Indoor Relative Humidity:		Outdoor Relative Humidity:	
Dew Point (inside).		Wind Speed	
Problem		Repair Priority:	
Emissivity:	0.95	Reflected Temperature:	71.6 °F
Camera Manufacturer	Fluke Thermography	Camera:	Ti400-14110349

Max = 103 0 Avg = 94,6 Min = 86:1	
CONTROL OF THE PROPERTY AND THE	
97.8	
NUMBER OF THE REST	85.4

AT000740.IS2



Visible Light Image

For SUBARNAS PROFESSIONAL SERVICES LLP

AUTHORISED SIGNATORY

NAS PROFESSIONAL SERVICES LLP

FA2 JSVM

COIMBATORE 641 015

subarnaas@gmail.com

GENGINE COMBATORE 641 104

Dr.M.JEYAKUMAR, M.E..Ph.D.

PRINCIPAL
CHRIST THE KING ENGINEERING COLLEGE,
Chikkarampalayam Village,
Karamadai. Mettupalayam Taluk,
Coimbatore - 641 104.





